



Photo 1 – Photo of damaged airplane (Photo courtesy of the pilot)



Photo 2 – View of damaged empennage (Photo courtesy of the pilot)



Photo 3 – View of damaged left main landing gear tire (Photo courtesy of the pilot)