



Photo 1 – View of accident airplane (Photo courtesy of the FAA)



Photo 2 – View of damaged right wing and aileron (Photo courtesy of the FAA)



Photo 3 – View of separated right landing gear (Photo courtesy of the FAA)