



Photo 1 – View of separated right landing gear wheel and tire (Courtesy of FAA)




Photo 2 – View of damage to right side landing gear attachment bolts and wheel hub (Courtesy of FAA)



Photo 3 – View of damage to outer wheel, inner race and bearings (Courtesy of FAA)