




**Photo 1 – View of damaged fuselage (Photo courtesy of the FAA)**



**Photo 2 – View of buckled interior floorboard (Photo courtesy of the FAA)**