



Photo 1 – View of damage to left wing and fuselage (Courtesy of FAA)



Photo 2 – View of damage to fuselage below the left wing (Courtesy of FAA)



Photo 3 – View of damage to outboard left wing (Courtesy of FAA)