



Photo 1 – View of airplane off runway (Photo courtesy of the FAA)



Photo 2 – View of damaged left horizontal stabilizer (Photo courtesy of the FAA)