



Photo 1 – View of accident airplane (Photo courtesy of the FAA)



Photo 2 – View of damaged forward fuselage (Photo courtesy of the FAA)



Photo 3 – View of damaged left tire/rim (Photo courtesy of the FAA)



Photo 4 – View of tire/rim mark left on runway (Photo courtesy of the FAA)