



Photo 1 – View of damage to the fuselage (Courtesy of FAA)




Photo 2 – View of damage to the right aileron (Courtesy of FAA)



Photo 3 – View of damage to the rudder (Courtesy of FAA)