



Photo 1 – View of left wing damage (Courtesy of the FAA)



Photo 2 – View of empennage damage (Courtesy of the FAA)



Photo 3 - View of fuselage damage (Courtesy of the FAA)