



Photo 1 – View of damage to the right wing forward spar (Courtesy of FAA)