



Photo 1 – View of damaged left wing (Photo courtesy of the FAA)



Photo 2 – View of damaged elevator (Photo courtesy of the FAA)



Photo 3 – View of damaged tailwheel (Photo courtesy of the FAA)