



Photo 1 – View of damage to left wing and lower fuselage (courtesy of the FAA)



Photo 2 – View of damaged taxiway sign (courtesy of the FAA)



Photo 3 – View of damaged left-wing spar (courtesy of the FAA)