



Photo 1 – View of damage to the right wing (Courtesy of FAA)



Photo 2 – View of damage to the right wing rib (Courtesy of FAA)