

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Spanish Fork State: UT

ZIP: 84660 Country: USA

Latitude: 40.1449333 Longitude: -111.6666943

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 09/13/2018 Local Time: 08:30
mm/dd/yyyy

Time Zone: Mountain

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N7223J

Manufacturer: Piper

Model: Cherokee

Serial Number: Unknown

Year of Manufacture: 1967

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 2150 lbs

Weight at Time of Accident/Incident: 1992 lbs

Number of Seats: 4 Flight Crew Seats: 2

Cabin Crew Seats: N/A Passenger Seats: 2

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☒ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	<u>Lycoming</u>	<u>O-320-E3D</u>			<u>150</u>	<u>1700</u>		
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: _____
mm/dd/yyyy

Airframe Total Time: _____ hrs

hours measured at (Select one)

- ☐ Last Inspection ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
☐ Specify: _____

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: Unknown

Model or Part No.: Unknown

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☐ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☐ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☐ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Dewey J Levie Family LTD PartnershipCity: ProvoState: UTZIP: 84606Fractional Ownership Aircraft: ☒ Yes ☐ NoCountry: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☒ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Spanish Fork - Woodhouse FieldDistance From Airport Center: 0 smAirport Identifier: KSPKDirection From Airport: N/A degrees trueProximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/AAirport Elevation: 4529 ft. msl**Runway Information**Runway ID: 30 (L/R/C) Length: 6500 ft Width: 100 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☒ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☒ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

“Flight Crewmember 1” Responsibilities at the Time of Accident/Incident ☐ Pilot ☐ Co-Pilot ☐ Student Pilot ☒ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew “Flight Crewmember 1” was pilot flying ☐ Yes ☐ No											
“Flight Crewmember 1” Identification First Name: <u>Colton</u> Middle Initial: <u>B</u> Last Name: <u>Mayberry</u> Age at time of Accident/Incident: <u>28</u> Date of Birth: <u> </u> <i>mm/dd/yyyy</i> Certificate Number: <u> </u>						City of Residence: <u>Provo</u> State: <u>UT</u> ZIP: <u>84601</u> Country: <u>USA</u>					
Degree of Injury ☐ None ☐ Fatal ☒ Minor ☐ Unknown ☐ Serious		Seat Occupied ☐ Left ☐ Front ☐ Unknown ☒ Right ☐ Rear ☐ Center ☐ Single		Restraint Type Available ☐ None ☒ Lap only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☒ Lap only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown			Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown				
Pilot Certificate(s) <i>(Check all that apply)</i> ☐ None ☒ Flight Instructor ☒ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer											
Principal Occupation ☒ Pilot ☐ Other ☐ Unknown		Medical Certificate ☐ None ☐ Class 3 ☒ Class 1 ☐ Driver’s License (Sport Pilot only) ☐ Class 2 ☐ Unknown		Medical Certificate Validity ☒ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance			Date of Last Medical <u>02/21/2018</u> <i>mm/dd/yyyy</i>				
Medical Certificate Limitations <u>N/A</u>											
Medical Certificate Special Issuance <u>N/A</u>											
Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: <u>04/19/2017</u> <i>mm/dd/yyyy</i>			Flight Review Aircraft Make: <u>Piper</u> Model: <u>PA24 Comanche</u>								
Airplane Rating(s) <i>(Check all that apply)</i> ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea		Other Aircraft Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift		Instrument Rating(s) <i>(Check all that apply)</i> ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift		Instructor Rating(s) <i>(Check all that apply)</i> ☐ None ☒ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport					
Type Ratings <u>N/A</u>						Student Endorsements <i>(Include dates)</i>					
Flight Time <i>(Enter appropriate number of hours in each box)</i>		All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
							Actual	Simulated			
Total Time	888	198	885	1	136	9	83	2	0	0	
Pilot in Command (PIC)	856	198	856	0	132	9	77	0	0	0	
Time as Instructor	555	174	555	0	52	0	16	0	0	0	
This Make/Model					40	0	0				
Last 90 Days	47	40	47	0	15	0	0	0	0	0	
Last 30 Days	10	10	10	0	1	0	0	0	0	0	
Last 24 Hours	1	1	1	0	0	0	0	0	0	0	

“Flight Crewmember 2” Responsibilities at the Time of Accident/Incident

“Flight Crewmember 2” was pilot flying ☐ Yes ☐ No

First Name: Chad City of Residence: Highland
Middle Initial: C State: UT ZIP: 84003
Last Name: Rasmussen Country: USA
Age at time of Accident/Incident: 35 Date of Birth: mm/dd/yyyy
Certificate Number: Not yet issued

Degree of Injury ☐ None ☐ Fatal ☒ Minor ☐ Unknown ☐ Serious	Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type Available ☐ None ☒ Lap only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☒ Lap only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Pilot Certificate(s) <i>(Check all that apply)</i> ☒ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer			

Principal Occupation	Medical Certificate	Medical Certificate Validity	Date of Last Medical
☐ Pilot ☒ Other ☐ Unknown	☐ None ☒ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown	☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance	<u>08/30/2018</u> <i>mm/dd/yyyy</i>

Must wear corrective lenses

**Date of Last Flight Review
or Equivalent, Including
FAR 121/135 Checks:**

Make: N/A

Model: N/A

Airplane Rating(s) (Check all that apply)	Other Aircraft Rating(s) (Check all that apply)	Instrument Rating(s) (Check all that apply)	Instructor Rating(s) (Check all that apply)
☒ None ☐ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	☒ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	☒ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	☒ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport

Student Endorsements *(Include dates)*

[illegible]

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KSPK</u> City: <u>Spanish Fork</u> State: <u>UT</u> Country: <u>USA</u>	Time of Departure Time: <u>08:30</u> Time Zone: <u>Mountain</u>	Destination Airport ID: <u>KSPK</u> City: <u>Spanish Fork</u> State: <u>UT</u> Country: <u>USA</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☐ No ☐ Unknown
--	--	---	--

Type of ATC Clearance/Service (Check all that apply) ☒ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise ☐ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA			
Airspace where the accident/incident occurred (Check all that apply) ☐ Class A ☒ Class G ☐ Military Operations Area (MOA) ☐ Special ☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area ☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown ☐ Class D ☐ Prohibited Area ☐ TRSA ☐ Class E ☐ Restricted Area ☐ FAR 93			Altitude of In-Flight Occurrence: <u>N/A</u> ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information (Check all that apply) ☒ National Weather Service ☐ Company ☐ Flight Service Station ☐ Military ☐ TV/Radio ☒ Internet ☐ Automated Report ☐ None ☐ Commercial Weather Service (DUATS) ☐ Unknown ☐ On-Board Weather		Weather Observation Facility Facility ID: _____ Observation Time: _____ Time Zone: _____ Distance from Accident Site: _____ nm Direction from Accident Site: _____ degrees true	
Basic Conditions ☒ VMC ☐ IMC ☐ Unknown	Light Condition ☒ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown ☐ Day ☐ Night ☐ Bright Night		
Sky/Lowest Cloud Condition ☒ Clear ☐ Thin Broken ☐ Few ☐ Thin Overcast ☐ Partial Obscuration ☐ Unknown ☐ Scattered Lowest Cloud Condition Height _____ ft agl	Ceiling ☒ None (Clear) ☐ Obscured ☐ Broken ☐ Indefinite ☐ Overcast ☐ Unknown Ceiling Height _____ ft agl	Temperature: <u>18</u> (C) or _____ (F) Dew Point: <u>5</u> (C) or _____ (F) Altimeter Setting: <u>30.07</u> in. Hg or _____ MB	
Wind Direction ☐ Variable -or- Direction: _____ degrees true	Wind Speed ☒ Calm ☐ Light and Variable -or- Speed: _____ kts	Wind Gusts ☒ Not Gusting -or- Speed: _____ kts	Visibility <u>+6SM</u> miles RVR: _____ feet RVV: _____ miles Density Altitude: <u>5700</u> ft
Intensity of Precipitation ☐ Light ☐ Moderate ☐ Heavy ☒ N/A ☐ Unknown	Type of Precipitation (Check all that apply) ☒ None ☐ Drizzle ☐ Freezing Rain ☐ Rain ☐ Ice Pellets ☐ Snow Shower ☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower ☐ Hail ☐ Snow Grains ☐ Freezing Drizzle ☐ Rain Showers ☐ Ice Crystals		Restriction to Visibility (Check all that apply) ☒ None ☐ Fog ☐ Blowing Dust ☐ Ground Fog ☐ Blowing Sand ☐ Haze ☐ Blowing Snow ☐ Ice Fog ☐ Blowing Spray ☐ Smoke ☐ Dust ☐ Unknown
Icing Forecast Amount ☒ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown Type ☒ N/A ☐ Rime ☐ Clear ☐ Mixed ☐ Unknown	Icing Actual Amount ☒ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown Type ☒ N/A ☐ Rime ☐ Clear ☐ Mixed ☐ Unknown		Turbulence Type (Check all that apply) ☒ None ☐ Clear Air ☐ Terrain-Induced ☐ Convective Turbulence Severity ☐ Light ☐ Moderate ☐ Severe ☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

None

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Aircraft frame, engine, and propeller sustained substantial damage. No damage to property other than aircraft and contents.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

The two pilots met at the Spanish Fork airport at 07:30. First, the pre-flight inspection was performed. No discrepancies were found. Weight and balance calculations were performed and found within limits. The instructor discussed the flight plan with the student. It was to be a local flight focusing on the basics of flight wherein the student would be allowed to fly the aircraft and familiarize himself with the basics of airmanship. The instructor explained use of seatbelts, emergency procedures, and positive exchange of controls. The aircraft was started and taxied over to the fuel pumps. The student was permitted to start the aircraft and taxi to the fuel pump with the instructor in the right seat prompting and aiding as necessary.

The aircraft was shut down again at the fuel pump, grounded, and fueled for the flight. Each tank was filled between 3/4 full and full. The fuel caps were replaced and the ground cable was removed. The aircraft was pushed back away from the pump where the pilots entered and restarted the aircraft. The pre-flight checks continued normally, including listening to the automated weather information broadcast, setting the instruments up for flight, and checking all flight controls and engine performance in the run-up. There were no problems throughout these steps.

At approximately 08:30, after performing all pre-flight checks, the pilots taxied the aircraft onto runway 30 at Spanish Fork and applied takeoff power. Engine performance was nominal and the runway centerline was maintained until reaching rotate speed. Upon reaching rotation speed, the student relaxed his feet from off the pedals causing the aircraft to drift left off the centerline. The student quickly replaced his feet on the pedals and pushed on the right brake causing the aircraft to veer sharply right. The instructor pushed the left rudder pedal to counteract the student's overcorrection. This brought the aircraft back in line with the runway, but not before the aircraft departed the runway to the right side at a speed near Vr. Departing the runway, the tail was heard striking the ground or bushes near the ground. This necessitated abortion of the takeoff (in case flight controls had been damaged). There was not sufficient airspeed and altitude to return to the runway. The instructor performed an emergency landing parallel to runway 30 about 25 to 30 feet off the right side of the runway. The aircraft was heavily damaged on large mounds of dirt and a ditch beside the runway, which sheared off all of the landing gear and bent the fuselage in half where it came to rest.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

Recommend that the airport surface adjacent to the runway is leveled and cleared of obstructions such as dirt mounds, ditches, bushes, and uneven terrain.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☐ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Unknown

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

49 Gallons

Fuel Type☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure****EVACUATION OF AIRCRAFT**Was an emergency evacuation of the aircraft performed? ☒ Yes ☐ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

After the accident, the instructor immediately shut down all electrical equipment and the magnetos switch and opened the door on his side. Both occupants quickly exited the aircraft under their own power through the door. Both wings were also bent upward in the crash when the aircraft came to rest in the ditch. The occupants climbed up the wing to get out of the ditch and left the scene of the accident.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number**

Manufacturer: _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

Due to the bent fuselage, it was not possible for me to access the ELT. I am not sure if it was activated or not. There have been delays contacting the mechanic and accessing the maintenance logs to the aircraft. I should be able to access them soon, but this form is due today so I have decided to send it as-is.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

09/24/2018

mm/dd/yyyy

Name of Pilot/Operator: Colton Beck Mayberry

Signature: 

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.
GAA18CA553

Reviewed by NTSB Regional Office
GAA

Name of Investigator
Eric Swenson

Date Report Received
09/27/2018