




Photo 1 – View of damage to the lower fuselage (Courtesy of FAA)



Photo 2 – View of damage to the lower fuselage intermediate bulkhead (Courtesy of Repair Station)