



Photo 1 – View of damage to airplane (Photo courtesy of the FAA)



Photo 2 – View of damage to bottom of right wing (Photo courtesy of the FAA)



Photo 3 – View of buckled structural rib of right wing (Photo courtesy of the FAA)