



Photo 1 – View of accident airplane inverted (Photo courtesy of the FAA)



Photo 2 – View of damaged left wing and empennage (Photo courtesy of the FAA)