



Photo 1 – View of damage to left wing (courtesy of the FAA)




Photo 2 – View of wrinkle damage to firewall (courtesy of the FAA)