



Photo 1 – View of damaged left wing (Photo courtesy of the FAA)



Photo 2 – View of damaged right wing lift strut (Photo courtesy of the FAA)