



Photo 1 – View of damaged windscreen (Photo courtesy of the mechanic)



Photo 2 – View of damaged fuselage (Photo courtesy of the mechanic)



Photo 3 – View of damaged right wing (Photo courtesy of the mechanic)