



Photo 1 – View of airplane with a collapsed nose landing gear on the runway (courtesy of the FAA)



Photo 2 – View of engine frame damage (courtesy of the FAA)