



Photo 1 – View of damaged airplane nosed down in snow bank (Photo courtesy of FAA)



Photo 2 – View of damaged left wing (Photo courtesy of the FAA)