



Photo 1 – View of damaged right wing (Photo courtesy unknown)



Photo 2 – View of separated engine (Photo courtesy unknown)



Photo 3 – View of accident airplane with latitude and longitude coordinates (Photo courtesy of the FAA)




Photo 4 – Screen capture of distance from end of runway to accident site