



Photo 1 – View of damage to the leading edge of the left wing (Courtesy of FAA)



Photo 2 – View of damage to the left wing and aileron (Courtesy of FAA)