



Photo 1 – View of right, front fuselage damage (photo courtesy of the FAA).



Photo 2 - View of fuselage damage (photo courtesy of the FAA).



Photo 3 - View of left wing damage (photo courtesy of the FAA).



Photo 4 - View of wing damage (photo courtesy of the FAA).




Photo 5 - View of empennage damage (photo courtesy of the FAA).