



Photo 1 – View of elevator damage (photo curtesy of law enforcement)



Photo 2 - View of wing damage (photo courtesy of law enforcement)



Photo 3 - View of left wing damage (photo courtesy of law enforcement)



Photo 4 – View of fuselage damage (photo courtesy of law enforcement)