



Photo 1 – View of damaged airport sign (Photo courtesy of the FAA)



Photo 2 – View of damaged left wing lift strut (Photo courtesy of the FAA)