




Photo 1 – View of damage to the left aileron of N733ND (Courtesy of FAA)



Photo 2 – View of damage to the left wing root of N9101X (Courtesy of FAA)