



Photo 1 – View of damage to the fuselage above the left main landing gear attachment points (Courtesy of FAA)



Photo 2 – View of damage to the lower fuselage beneath the left main landing gear attachment points (Courtesy of FAA)