



Photo 1 – Front view of fuselage and cowling damage (photo courtesy of the FAA)



Photo 2 - View of lower engine mount to airframe damage (photo courtesy of the FAA)