



Photo 1 – View of damage to right wing (Courtesy of the FAA)



Photo 2 – View of damage to right aileron (Courtesy of the FAA)