



Photo 1 – View of left wing damage (photo courtesy of the FAA)



Photo 2 - View of fuselage and cowling damage (photo courtesy of the FAA)



Photo 3 - View of aft fuselage damage (photo courtesy of the FAA)