

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Saginaw State: TX
 ZIP: 76179 Country: USA
 Latitude: 32.93 N Longitude: 97.41 W
(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 04/04/2019 Local Time: 1810
mm/dd/yyyy Time Zone: Central

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N801R

Manufacturer: Zenith (kit manufacturer)

Model: CH 801

Serial Number: 8-4296

Year of Manufacture: 2005

Amateur-Built: ☒ Yes ☐ No If Yes: ☒ Kit/Plans ☐ Original Design Make: David Runyan-builder

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 2250 lbs

Weight at Time of Accident/Incident: 2041 lbs

Number of Seats: 4 Flight Crew Seats: 1

Cabin Crew Seats: 0 Passenger Seats: 3

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☐ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☒ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

- ☐ Retractable

- ☒ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type *(Select one)*

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type *(Reciprocating)*

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. <i>mm/dd/yyyy</i>	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time <i>(hours)</i>	Time Since: Inspection <i>(hours)</i>	Overhaul <i>(hours)</i>
Eng. 1	Superior	XP-0-360-A1A2	03384	10/28/2003	180	445	8	n/a
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☒ Conditional Inspection
☐ Annual ☐ Unknown

Date Last Inspection: 12/31/2018
mm/dd/yyyy

Airframe Total Time: 445 hrs
 hours measured at *(Select one)*
☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program *(Select one)*

- ☐ Annual
☒ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
☒ Specify: Hand-held pressurized bottle

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: Sensenich

Model: 76EM8

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: Ameri-King

Model or Part No.: AK-450

TSO No.: ☐ C91 (121.5 MHz) ☒ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft: ☐ Yes ☒ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment *(Check all that apply)*

- ☒ ADS-B
☐ Airframe Parachute
☒ Angle of Attack Indicator
☒ Autopilot
☐ Data Recorder
☒ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☒ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: David S RunyanCity: Fort WorthFractional Ownership Aircraft: ☐ Yes ☒ NoState: TX ZIP: 76179Country: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Fire fighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Hicks AirfieldDistance From Airport Center: 0.1 smAirport Identifier: T67Direction From Airport: 200 degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 855 ft. msl**Runway Information**Runway ID: 32 (L/R/C) Length: 3740 ft Width: 60 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: David City of Residence: Fort Worth
 Middle Initial: S State: TX ZIP: 76179
 Last Name: Runyan Country: USA
 Age at time of Accident/Incident: 67 Date of Birth: mm/dd/yyyy
 Certificate Number: mm/dd/yyyy

Degree of Injury

☒ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☒ Left
 ☐ Front
 ☐ Unknown
☐ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available
☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown
Used
☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☐ Flight Instructor
 ☒ Commercial
 ☐ US Military
☒ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
☒ Other
☐ Unknown

Medical Certificate

☐ None
 ☒ Class 3
☐ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
☒ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

06/06/2017
 mm/dd/yyyy

Medical Certificate Limitations

Must have available glasses for near vision

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

06/27/2015
 mm/dd/yyyy

Flight Review Aircraft

Make: Zenith
 Model: CH 801

Airplane Rating(s)

(Check all that apply)
☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)
☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☒ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)
☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)
☒ None
☐ Airplane Single-Engine
☐ Airplane Multi-Engine
☐ Gyroplane
☐ Powered Lift
☐ Instrument Airplane
☐ Instrument Helicopter
☐ Helicopter
☐ Glider
☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	729	445	749	0	31	6	75	1500	0	0
Pilot in Command (PIC)	686	445	685	0	31	0	0	1500	0	0
Time as Instructor	0	0	0	0	0	0	0	0	0	0
This Make/Model					18	0	0			
Last 90 Days	7	7	7	0	0	0	0	0	0	0
Last 30 Days	4	4	4	0	0	0	0	0	0	0
Last 24 Hours	1	1	1	0	0	0	0	0	0	0

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____
 Model: _____

Airplane Rating(s)

(Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)										
Crew Name and Address					Seat Occupied		Injury			
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown			
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown			
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs							
Crew Name and Address					Seat Occupied		Injury			
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown			
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown			
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs							
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)										
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age		
First Name: <u>William</u> City: <u>Fort Worth</u> Middle Initial: <u>S</u> State: <u>TX</u> ZIP: <u>76244</u> Last Name: <u>Runyan</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☒ Left ☐ Center ☐ Right ☐ Unknown Row: <u>2</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>Tara</u> City: <u>Dubuque</u> Middle Initial: _____ State: <u>IA</u> ZIP: _____ Last Name: <u>Herbst</u> Country: <u>USA</u> ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☒ Right ☐ Unknown Row: <u>1</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point

Airport ID: T67
 City: Fort Worth
 State: TX
 Country: USA

Time of Departure

Time: 1745
 Time Zone: Central

Destination

Airport ID: T67
 City: Fort Worth
 State: TX
 Country: USA

Type Flight Plan Filed

☒ None ☐ VFR/IFR
☐ Company VFR ☐ IFR
☐ Military VFR ☐ Unknown
☐ VFR
 Activated? ☐ Yes ☐ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

☐ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☐ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☒ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☒ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence:

900 ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☐ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV/Radio ☐ Internet
☐ Automated Report ☐ None
☐ Commercial Weather Service (DUATS) ☐ Unknown
☒ On-Board Weather

Weather Observation Facility

Facility ID: KAFW
 Observation Time: 1500
 Time Zone: Central
 Distance from Accident Site: 6 nm
 Direction from Accident Site: 045 degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☐ Clear ☐ Thin Broken
☒ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

3000 ft agl

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

 ft agl

Temperature: (C) or 70 (F)

Dew Point: (C) or (F)

Altimeter Setting: field eleva in. Hg
 or MB

Wind Direction

☐ Variable

-or-
 Direction: 050 degrees true

Wind Speed

☐ Calm
☐ Light and Variable

-or-
 Speed: 10 kts

Wind Gusts

☐ Not Gusting

-or-
 Speed: 15-20 estima kts

Visibility more than 6 miles

RVR: feet

RVV: miles

Density Altitude: ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

☒ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

Amount ☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Icing Actual

Amount ☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Turbulence

Type (Check all that apply) ☒ None ☐ Light
☐ Clear Air ☐ Moderate
☒ Terrain-Induced ☐ Severe
☐ Convective Turbulence ☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

none

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☐ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☐ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Aircraft damage: Prop spinner destroyed, propeller destroyed, engine cowling destroyed, carburetor airbox destroyed, engine exhaust destroyed, firewall damaged, engine mount bent, cabin floor had slight buckle in the vicinity of the rudder pedals, right wing tore loose from rear fitting and rotated forward approx. 1 foot and down 1 or 2 feet, left wing top skin buckled on inboard side, left wing sustained 2 inch hole near pitot tube, left wingtip crumpled on leading edge, fuselage deformed on both sides from force of wings transmitted through the struts, 4 windows broken, 1 inch deep dent on leading edge of left horizontal stabilizer, elevator jammed in place due to aircraft's impact, main landing gear bent, nose gear sheared off

No damage to other property

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

N801R, a four-place, all-aluminum, experimental Zenith CH801, departed Hicks Airfield (T67), near Fort Worth, TX at 1745 hours CST on 04/04/2019 on a local pleasure flight. The aircraft contained 3 occupants. The flight lasted approx. 25 minutes, at which time N801R returned to T67 from the west and entered a left downwind leg to runway 32. The wind was northeasterly at approx. 10 knots with occasional gusts. The wind direction resulted in a ninety degree crosswind to the runway.. The aircraft turned to a base leg, then a final leg, with an approach speed of 65 mph, 5 mph higher than normal due to wind gusts. Engine rpm was approx. 1400. On final approach, crosswinds were such that the pilot had no trouble maintaining alignment with the runway centerline with very minimal slipping into the wind required.

At an altitude of fifty feet or less, verified with an onboard cellphone video recording that showed the altimeter, the aircraft suddenly rolled to the left approx. 30 degrees as a result of a strong wind gust from the right. The pilot applied full right aileron, but the aircraft was very slow to respond, not obtaining a wings-level attitude until the aircraft had descended to an altitude of only a few feet above the ground and well left of the runway centerline. Although full power was applied, contact with the ground ensued. The video recording showed that initial contact with the ground occurred approx. 2.5 seconds after the right wing became elevated due to the wind gust. If the video is viewed frame-by-frame it is apparent that the video ends because the force of impact jars the cellphone from the passenger's hand.

No damage was done to any property other than the aircraft.

No occupants were injured.

The video was made on the cellphone of the back seat passenger, Will Runyan. The video has been forwarded to the NTSB investigator.

Post-crash still photos of the instrument panel at the accident site show that the altimeter was set to field elevation; hence, altimeter readings on the video are accurate.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

It would have been difficult to have avoided the accident; however, in the future, this pilot intends to institute a hard and fast rule, that, on final approach, if any control surface hits its stop, an immediate go-around will be initiated.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Total Time/Cycles
On Part

_____ Hours

_____ Cycles

Time Since This Part
Inspected/Overhauled

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff

(Convert from pounds, as necessary)

39 Gallons

Fuel Type

☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive

Other Services, if Any, Prior to Departure

none.

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☒ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

Pilot-left door

Passengers-right door

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed☐ Minor☐ Substantial☒ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

Page 4-"Airport Information"- Accident was listed as off-airport because aircraft came to final rest on railroad right-of-way

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

4/11/2019

mm/dd/yyyy

Name of Pilot/Operator: David Runyan

Signature: _____

– or – ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

– or – ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

GAA19CA200

Reviewed by NTSB Regional Office

GAA

Name of Investigator

Eleazar Nepomuceno

Date Report Received

4/11/2019