



Photo 1 – View of damaged fuselage (Photo courtesy of the FAA)



Photo 2 – View of damaged fuselage from underneath (Photo courtesy of the FAA)