

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Bethel State: AK
 ZIP: 99559 Country: United States of America
 Latitude: 60.7797 Longitude: 161.8378
(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 05/01/2019 Local Time: 8:18PM
mm/dd/yyyy Time Zone: AKST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N524AV

Manufacturer: GippsAero

Model: GA8 Airvan

Serial Number: GA8-15-214

Year of Manufacture: 2015

Amateur-Built: ☒ Yes ☐ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 4000 lbs

Weight at Time of Accident/Incident: 3905 lbs

Number of Seats: 7 Flight Crew Seats: 1

Cabin Crew Seats: 0 Passenger Seats: 6

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☒ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type *(Select one)*

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type *(Reciprocating)*

- ☐ Carburetor ☒ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. <i>mm/dd/yyyy</i>	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time <i>(hours)</i>	Time Since: Inspection <i>(hours)</i>	Overhaul <i>(hours)</i>
Eng. 1	Lycoming	IO-540-K1A5	L-18804-48E	unk	300	5397.2	47.2	47.2
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☒ AAIP ☐ Conditional Inspection
☐ Annual ☐ Unknown

Date Last Inspection: 04/15/2019
mm/dd/yyyy

Airframe Total Time: 4437.0 hrs

hours measured at *(Select one)*

- ☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program *(Select one)*

- ☐ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☒ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
☒ Controllable Pitch
☐ Ground Adjustable

Manufacturer: Hartzell

Model: HC-C3YR-1RF/F8068

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: Artex

Model or Part No.: _____

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☒ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☐ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☒ Unknown

Additional Equipment *(Check all that apply)*

- ☒ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☒ Electronic Multifunction Display
☒ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☒ Onboard Weather
☒ Satellite Tracking Device
☒ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Global Air Concepts LLCFractional Ownership Aircraft: ☐ Yes ☒ NoCity: AnchorageState: AKZIP: 99502Country: United States of America**Operator of Aircraft**☐ Same As Registered OwnerName: Grant Aviation

Doing Business As: _____

Air Carrier/Operator Designator (4 Character Code): ENAH☐ Same Address as Registered OwnerCity: AnchorageState: AKZIP: 99502Country: United States of America**Operating Certificates Held**

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☒ Commuter Air Carrier (FAR 135)
☒ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☐ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☒ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☒ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☒ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Fire fighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Bethel AirportAirport Identifier: PABEProximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/A

Distance From Airport Center: _____ sm

Direction From Airport: _____ degrees true

Airport Elevation: 129 ft. msl**Runway Information**

Runway ID: _____ (L/R/C) Length: _____ ft Width: _____ ft

Runway/Landing Surface (Check all that apply)

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☒ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☒ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Chad City of Residence: Pullman
 Middle Initial: T State: WA ZIP: 99163
 Last Name: Roberts Country: United States of America
 Age at time of Accident/Incident: 24 Date of Birth: [REDACTED] mm/dd/yyyy
 Certificate Number: [REDACTED]

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☒ 4-point</td> <td>☒ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☐ 3-point	☐ 3-point	☒ 4-point	☒ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☐ 3-point	☐ 3-point																
☒ 4-point	☒ 4-point																
☐ 5-point	☐ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) <table style="width: 100%;"> <tr> <td>☐ None</td> <td>☒ Flight Instructor</td> <td>☒ Commercial</td> <td>☐ US Military</td> </tr> <tr> <td>☐ Private</td> <td>☐ Recreational</td> <td>☐ Airline Transport</td> <td>☐ Foreign</td> </tr> <tr> <td>☐ Student</td> <td>☐ Sport</td> <td>☐ Flight Engineer</td> <td></td> </tr> </table>				☐ None	☒ Flight Instructor	☒ Commercial	☐ US Military	☐ Private	☐ Recreational	☐ Airline Transport	☐ Foreign	☐ Student	☐ Sport	☐ Flight Engineer			
☐ None	☒ Flight Instructor	☒ Commercial	☐ US Military														
☐ Private	☐ Recreational	☐ Airline Transport	☐ Foreign														
☐ Student	☐ Sport	☐ Flight Engineer															

Principal Occupation ☒ Pilot ☐ Other ☐ Unknown	Medical Certificate ☐ None ☐ Class 3 ☒ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown	Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance	Date of Last Medical <u>04/11/2019</u> mm/dd/yyyy
---	---	---	--

Medical Certificate Limitations

Must Wear Corrective Lenses

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: <u>02/27/2019</u> mm/dd/yyyy	Flight Review Aircraft Make: <u>GippsAero</u> Model: <u>GA8 Airvan</u>
---	---

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☐ None ☒ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
---	---	--	--

Type Ratings	Student Endorsements (Include dates)
---------------------	---

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	783	129	783	0	39	1	79	0	0	0
Pilot in Command (PIC)	733	129	733	0	34	1	79	0	0	0
Time as Instructor	202	0	202	0	2	0	0	0	0	0
This Make/Model					0	0	0			
Last 90 Days	123	110	123	0	2	0	0	0	0	0
Last 30 Days	63	58	63	0	2	0	0	0	0	0
Last 24 Hours	5	5	5	0	0	0	0	0	0	0

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____
 Model: _____

Airplane Rating(s)

(Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Private ☐ Recreational ☐ Student ☐ Sport ☐ Commercial ☐ US Military ☐ Airline Transport ☐ Foreign ☐ Flight Engineer					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Private ☐ Recreational ☐ Student ☐ Sport ☐ Commercial ☐ US Military ☐ Airline Transport ☐ Foreign ☐ Flight Engineer					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: <u>Adolf</u> City: <u>Tunutuliak</u> Middle Initial: _____ State: <u>AK</u> ZIP: <u>99680</u> Last Name: <u>Lupie</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☒ Unknown Row: <u>1</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☒ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☒ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>April</u> City: <u>Tuntutuliak</u> Middle Initial: <u>C</u> State: <u>AK</u> ZIP: <u>99680</u> Last Name: <u>Morgan</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☒ Unknown Row: <u>2</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>Elena</u> City: <u>Eek</u> Middle Initial: <u>C</u> State: <u>AK</u> ZIP: <u>99578</u> Last Name: <u>Stevn</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☒ Unknown Row: <u>2</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>Agnes</u> City: <u>Kongiganak</u> Middle Initial: <u>R</u> State: <u>AK</u> ZIP: <u>99545</u> Last Name: <u>Andrew</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☒ Unknown Row: <u>3</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>A61</u> City: <u>Tuntutuliak</u> State: <u>Alaska</u> Country: <u>United States of America</u>	Time of Departure Time: <u>7:39pm</u> Time Zone: <u>AKST</u>	Destination Airport ID: <u>PABE</u> City: <u>Bethel</u> State: <u>Alaska</u> Country: <u>United States of America</u>	Type Flight Plan Filed ☐ None ☐ VFR/IFR ☒ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☒ Yes ☐ No ☐ Unknown
---	---	--	--

Type of ATC Clearance/Service (Check all that apply)

☐ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☒ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A	☐ Class G	☐ Military Operations Area (MOA)	☐ Special	Altitude of In-Flight Occurrence: _____ ft msl
☐ Class B	☐ Demo Area	☐ Airport Advisory Area	☐ Air Traffic Control Area	
☐ Class C	☐ Warning Area	☐ Jet Training Area	☐ Unknown	
☒ Class D	☐ Prohibited Area	☐ TRSA		
☐ Class E	☐ Restricted Area	☐ FAR 93		

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☐ National Weather Service	☒ Company
☐ Flight Service Station	☐ Military
☐ TV/Radio	☒ Internet
☒ Automated Report	☐ None
☐ Commercial Weather Service (DUATS)	☐ Unknown
☒ On-Board Weather	

Weather Observation Facility

Facility ID: PABE ATIS

Observation Time: _____

Time Zone: AKST

Distance from Accident Site: _____ nm

Direction from Accident Site: _____ degrees true

Basic Conditions

☒ VMC

☐ IMC

☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown

☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☐ Clear ☐ Thin Broken

☐ Few ☐ Thin Overcast

☐ Partial Obscuration ☐ Unknown

☐ Scattered

Lowest Cloud Condition Height

3700 ft agl

Ceiling

☐ None (Clear) ☐ Obscured

☒ Broken ☐ Indefinite

☐ Overcast ☐ Unknown

Ceiling Height

4700 ft agl

Temperature: _____ (C) or 48 (F)

Dew Point: _____ (C) or 41 (F)

Altimeter Setting: 29.94 in. Hg
or _____ MB

Wind Direction

☐ Variable

-or-
Direction: 160 degrees true

Wind Speed

☐ Calm

☐ Light and Variable

-or-
Speed: 8 kts

Wind Gusts

☒ Not Gusting

-or-
Speed: _____ kts

Visibility 10 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light

☐ Moderate

☐ Heavy

☒ N/A

☐ Unknown

Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☒ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☒ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☒ None	☐ Light
☐ Clear Air	☐ Moderate
☐ Terrain-Induced	☐ Severe
☐ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Impact with shipping container caused damage to the LH wing-tip outside of the Pitot mast, crunching the fiberglass wingtip and denting the outboard side of the Pitot mast. This single impact point at the wing tip also resulted in wrinkled skin/trim panels near the LH wing-root towards the trailing edge of the wing. Later inspection by Grant Aviation mechanics with a bore-scope found rear spar cracking inboard on the LH wing. No damage was done to the shipping container.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

The weather for the majority of the flight consisted of rain showers and areas of low ceilings/visibility blowing through the area, but still legal VFR throughout the route. I had decided to wait for approximately 40 minutes on the ground at A61 for an area of heavy precipitation I had seen on the cockpit FIS-B weather display between A61 and PABE to move past before continuing my flight to PABE.

Once the weather had moved and dissipated, I departed for Bethel at 7:38PM AKST, picking a route towards PAEE to avoid going through the more severe radar echoes showing on the FIS-B display. Shortly after skirting the edge of one particularly large storm cell, I was relieved to brake out into an area of high overcast with nearly unlimited visibility approximately 15 to 20NM South of PABE. I continued the rest of the flight in good weather and landed in Bethel without any issues.

As I taxied the aircraft into the tie-down spot nearest to the Grant maintenance hangar, just as I have done for the past two weeks on shift while flying this particular airplane (N524AV does not have a Tanis heater, so it has been parked there and moved inside by maintenance over night once they made space for it), my attention was focused on not running the prop into the tie-down cones, and I was tired/relieved to be on the ground at the end of a long day with low weather, when the left wingtip struck the corner of a Ravn con-ex shipping container which had been recently re-positioned to that location within the last couple of days. The impact occurred taxiing at very low speed in a tight RH turn which I had initiated in order to line up the aircraft with the tie-down location.

Immediately following the wing-tip's impact, I shut down the engine and electrical system to secure the aircraft. The wingtip impact and subsequent aircraft shutdown occurred at approximately 8:18PM AKST. The passengers were all startled, but nobody was injured. I exited the airplane and confirmed that the wing-tip was the only impact point and that the area was safe/secure before assisting my passengers with exiting the aircraft. Crinkled skin near the wing root required the passengers to deplane through the pilot/co-pilot doors.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

"Wing Walkers" or Aircraft Marshaling by ground crew would have given me a second set of eyes while maneuvering into a tight parking spot such as this one.

In hindsight, I believe that fatigue also played a large factor. Especially given that I was approaching the end of my 14 hour duty day, I am relatively new to flying commercially in general, and that I am not very experienced at operating in the more stressful weather conditions/minimums which are considered VFR flying in Alaska.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Total Time/Cycles
On Part

_____ Hours

_____ Cycles

Time Since This Part
Inspected/Overhauled

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff

(Convert from pounds, as necessary)

~44 Gallons

Fuel Type

☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☐ Yes ☒ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

5 Passengers exited through the Pilot side (LH) front door of the aircraft. 1 Passenger seated in the RH front seat exited through the RH front door of the aircraft. Everyone was calm and orderly. There was no "emergency" or "evacuation" involved. The only reason for deplaning passengers in this manner was the bent wing-root trim which restricted the travel of the rear cabin door.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed☐ Minor☐ Substantial☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

Passengers cont.

Molly B Buzz Kongiganak, AK 99545 injury none

Nicole M Wood Kongiganak, AK 99545 injury none

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

05/04/2019

mm/dd/yyyy

Name of Pilot/Operator: Chad Trevett Roberts

Signature:

– or – ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

– or – ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

GAA19CA239

Reviewed by NTSB Regional Office

GAA

Name of Investigator

Eleazar Nepomuceno

Date Report Received

5/10/2019