



Photo 1 – View of nosed over airplane with damaged rudder (courtesy of the FAA)



Photo 2 - View of nosed over airplane with damaged right-wing lift strut (courtesy of the FAA)