



Photo 1 – View of damaged fuselage (Photo courtesy of the airport manager)



Photo 2 – View of left wing rear attach point to fuselage damage (Photo courtesy of the airport manager)