



Photo 1 – View of front damage to both wings (photo courtesy of the FAA)



Photo 2 - View of left wing damage (photo courtesy of the FAA)



Photo 3 - View of right wing damage (photo courtesy of the FAA)