



Photo 1 – View of wrinkled left wing (Photo courtesy of the pilot)



Photo 2 – View of damaged left wing from underneath (Photo courtesy of the pilot)