



Photo 1 – View of damaged left wing and left aileron (Photo courtesy of the pilot)



Photo 2 – View of tailwheel assembly with missing left steering spring (Photo courtesy of the airport manager)



Photo 3 – View of left steering spring found on runway (Photo courtesy of the pilot)