



Photo 1 – View of white runway scrape marking (Photo courtesy of airport operations)



Photo 2 – View of damaged right aileron (Photo courtesy of airport operations)



Photo 3 – View of damaged left aileron (Photo courtesy of airport operations)