



Photo 1 – View of inverted airplane with damage to the right wing (courtesy of the FAA)



Photo 2 – View of fuselage damage (courtesy of the FAA)



Photo 3 – View of recovered airplane with damage to both wings and fuselage (courtesy of the FAA)