



Photo 1 – View of fuselage and left and right wing damage (photo courtesy of the FAA)



Photo 2 - View of fuselage damage (photo courtesy of the FAA)



Photo 3 - View of horizontal stabilizer and elevator damage (photo courtesy of the FAA)