



Photo 1 – View of damage to the right wing rear spar (Courtesy of FAA)