



Photo 1 – View of damaged airplane on concrete barrier (courtesy of the operator)



Photo 2 – View of damaged floor board (courtesy of the FAA)