



Photo 1 – View of flat nose wheel (photo courtesy of the FAA)




Photo 2 - View of firewall damage (photo courtesy of the FAA)




Photo 3 - View of fuselage damage (photo courtesy of the FAA)