



**Photo 1 – View of collapsed nose landing gear and damaged fuselage (Photo courtesy of the FAA)**



**Photo 2 – View of damaged fuselage near left wing (Photo courtesy of the FAA)**