

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Lebanon State: IN

ZIP: 46052 Country: USA

Latitude: N40.0360756 Longitude: W-86.4822183

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 11/10/2019 Local Time: 1316
mm/dd/yyyy

Time Zone: Eastern

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N827MW

Manufacturer: Sikorsky

Model: SK58JT

Serial Number: 58-827

Year of Manufacture: 1958

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☐ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 12,500 lbs

Weight at Time of Accident/Incident: 10,000 lbs

Number of Seats: 7 Flight Crew Seats: 2

Cabin Crew Seats: _____ Passenger Seats: 5

Number of Engines: 2

Category of Aircraft

- ☐ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☒ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☐ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☒ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☐ Tricycle ☒ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel

☐ Other Launch/Recovery System

☐ None ☐ Unknown

Engine Type (Select one)

- ☐ Reciprocating ☐ Liquid Rocket
☒ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

☐ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Pratt & Whitney	PT6T-3	CP-PS 60134	05/1971	900	8641.3	1789.7	1824.8
Eng. 2	Pratt & Whitney	PT6T-3	CP-PS 61470	06/1978	900	14810.8	3185.6	3220.7
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☒ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☐ Annual ☐ Unknown

Date Last Inspection: 10/29/2019
mm/dd/yyyy

Airframe Total Time: 20047.0 hrs

hours measured at (Select one)

☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
☐ Conditional (Amateur-built only)
☒ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
☒ Specify: Fire Eye, Infrared

Propeller 1

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: AmeriKing

Model or Part No.: AK450-1

TSO No.: ☐ OC91 (121.5 MHz) ☒ OC91a (121.5 MHz)
☐ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft: ☐ Yes ☒ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☒ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☒ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☒ Handheld GPS
☐ Heads Up Display
☒ Onboard Weather
☒ Satellite Tracking Device
☐ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Midwest Truxton International, Inc.City: OrlandoState: FLZIP: 32827-7024Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: USA**Operator of Aircraft**☐ Same As Registered Owner☐ Same Address as Registered OwnerName: Midwest Helicopter Airways, Inc.City: Willowbrook

Doing Business As: _____

State: ILZIP: 60527Air Carrier/Operator Designator (4 Character Code): JTKA / JTKLCountry: USA**Operating Certificates Held**

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☒ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☒ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☒ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Fire fighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☒ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Boone Country AirportDistance From Airport Center: 2.95 smAirport Identifier: 6I4Direction From Airport: 309 degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 959 ft. msl**Runway Information**Runway ID: 18/36 (L/R/C) Length: 3600 ft Width: 30 ft**Runway/Landing Surface (Check all that apply)**

- ☐ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☒ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☒ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Aborted Landing (after touchdown)
☐ Crosswind ☒ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☒ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Randy City of Residence: Manteno
 Middle Initial: A State: IL ZIP: 60950
 Last Name: McCormick Country: USA
 Age at time of Accident/Incident: 50 Date of Birth: [REDACTED] mm/dd/yyyy
 Certificate Number: [REDACTED]

Degree of Injury ☐ None ☐ Fatal ☒ Minor ☐ Unknown ☐ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☒ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☒ 4-point</td> <td>☒ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☐ 3-point	☐ 3-point	☒ 4-point	☒ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☐ 3-point	☐ 3-point																
☒ 4-point	☒ 4-point																
☐ 5-point	☐ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☒ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer		Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance															
Principal Occupation ☒ Pilot ☐ Other ☐ Unknown	Medical Certificate ☐ None ☐ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☒ Class 2 ☐ Unknown	Date of Last Medical <u>05/14/2019</u> mm/dd/yyyy															

Medical Certificate Limitations

Glasses

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

07/23/2019
mm/dd/yyyy

Flight Review Aircraft

Make: Sikorsky
 Model: SK58

Airplane Rating(s) (Check all that apply) ☒ None ☐ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☒ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☐ None ☐ Airplane ☒ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☐ None ☐ Instrument Airplane ☐ Airplane Single-Engine ☒ Instrument Helicopter ☐ Airplane Multi-Engine ☒ Helicopter ☐ Gyroplane ☐ Glider ☐ Powered Lift ☐ Sport
---	--	--	---

Type Ratings

SK58
S70

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	5,500	1,450			500	100	200	5,500		
Pilot in Command (PIC)	4,500	1,350			400	80	150	4,500		
Time as Instructor	1,000				100	50	100	1,000		
This Make/Model					30					
Last 90 Days	60	10			10	2	6	60		
Last 30 Days	20	4			5	0	2	20		
Last 24 Hours	1	1			0	0	0	1		

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____
 Model: _____

Airplane Rating(s)

(Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply)					Restraint Type:		Inflatable Restraints		
☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer					Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply)					Restraint Type:		Inflatable Restraints		
☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer					Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: <u>Winston</u> City : <u>Algonquin</u> Middle Initial: <u>L</u> State: <u>IL</u> ZIP: <u>60102</u> Last Name: <u>Wheeler</u> Country: <u>USA</u> ☒ Crew ☐ Passenger ☐ Other			☒ Left ☐ Center ☐ Right ☐ Unknown Row: ____	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☒ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☒ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>Joel</u> City : <u>Kankakee</u> Middle Initial: <u>R</u> State: <u>IL</u> ZIP: <u>60901</u> Last Name: <u>Ramos</u> Country: <u>USA</u> ☒ Crew ☐ Passenger ☐ Other			☐ Left ☒ Center ☐ Right ☐ Unknown Row: ____	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☒ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☒ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: ____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: ____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point

Airport ID: KUMP
 City: Fishers
 State: IN
 Country: USA

Time of Departure

Time: 1300
 Time Zone: Eastern

Destination

Airport ID: N/A
 City: Lebanon
 State: IN
 Country: USA

Type Flight Plan Filed

☒ None ☐ VFR/IFR
☐ Company VFR ☐ IFR
☐ Military VFR ☐ Unknown
☐ VFR
 Activated? ☐ Yes ☐ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

☒ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☐ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☒ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☐ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence:

N/A ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☒ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV/Radio ☐ Internet
☒ Automated Report ☐ None
☐ Commercial Weather Service (DUATS) ☐ Unknown
☒ On-Board Weather

Weather Observation Facility

Facility ID: KTYQ
 Observation Time: 1815Z
 Time Zone: Eastern
 Distance from Accident Site: 10.5 nm
 Direction from Accident Site: 095 degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

 ft agl

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

 ft agl

Temperature: 12 (C) or 53.6 (F)

Dew Point: 05 (C) or 41 (F)

Altimeter Setting: 29.95 in. Hg
 or 1014.2 MB

Wind Direction

☐ Variable

-or-
 Direction: 200 degrees true

Wind Speed

☐ Calm
☐ Light and Variable

-or-
 Speed: 07 kts

Wind Gusts

☒ Not Gusting

-or-
 Speed: kts

Visibility 10 miles

RVR: feet

RVV: miles

Density Altitude: ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

☒ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

Amount ☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Icing Actual

Amount ☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Turbulence

Type (Check all that apply) ☒ None ☐ Light
☐ Clear Air ☐ Moderate
☐ Terrain-Induced ☐ Severe
☐ Convective Turbulence ☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

None

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

All four main rotor blades destroyed, tail boom destroyed from main rotor blade contact, tail pylon and tail rotor destroyed due to separation from airframe. Substantial damage to main airframe due to crushing of skin and spars from main rotor contact with tail boom. Main rotor head swash plate substantially damaged.

Additional significant damage was done to an empty semi-trailer.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible.

Departed KUMP at approximately 1300 local. Flew direct to the job site at 135 South Mount Zion Road. Upon arrival I realized that the units were on the west side of the building and not the east side as depicted on the paperwork and discussed with the customer at approximately 1230. I did a 270-degree orbital the west side of the building to look for obstacles and decide a course of action. Decided to land on the west side by the units because the customer had instructed to land by the units and they sometimes get the compass directions messed up. There was an occupied guard shack and truck on the south side of the area and numerous personnel and small cones around the center area. I decided to land to the north side of the area. I decided to approach heading 180 due to prevalent winds. I came to a 75' high hover due to the tightness and a light dust cloud that formed. My mechanic in the left seat said there was a trailer beneath us. I had noticed the trailer on my orbit and thought I had a good reference off my right to center me in an area south and clear of the trailer. I stated that I was coming right as I continued to come down and forward. My left seat mechanic said there was trash on the left. I had also seen the dumpster on that side during the orbit and didn't consider it an issue due to being filled with wood. As we descended, I asked my crew member in the belly of he could hop out after we landed and make sure we were in the correct area they wanted us to be. After landing as I looked inside to roll the throttles back to our idle speed, I felt one large bang followed by a series of bangs. The aircraft began to shake violently and I rolled the throttles completely off. As the blades coasted down the aircraft yawed and the blades collapsed. When the blades stopped, I told the crew to get out and shutoff the boost pumps, generators and battery. I then got out of the aircraft. I checked the condition of the crew and started our emergency response plan.

Randy A. McCormick

RECOMMENDATION (How could this accident/incident have been prevented?)**Operator/Owner Safety Recommendation**

Midwest Helicopter Airways, Inc. is currently reviewing all the information we have collected from pilot and MHA crew statements. We are also reviewing information about the job-site itself to see if something was missed in the pre-planning stages. MHA utilizes a SMS program on a daily basis for Ground Risk Assessments and Flight Risk Assessments. These assessments establish a point value for each task or flight being conducted. When the value reaches a certain point, managerial authorization is required, or a flight is not permitted. A hazard report is being made for this occurrence and it will then be assigned to an official at MHA to begin developing a corrective action.

During the pre-planning phase of this mission that was conducted last week, it was discussed on where the aircraft / equipment was going to be staged. The customer provided us a construction drawing of this building depicting the area in where they were going to stage from. This drawing was checked in comparison to Goggle Earth and this is when the concern over the dimensions for landing was brought up as from Goggle Earth you can see numerous semi-trailers at the facility. We have been to this location at least 2 time prior, but the customer said we would have only about 70' wide area to land. I explained to him that in the pre-lift checklist we gave them for review and for their signature, that we require a 100' by 150' area for landing and that they would more than likely have to move some tractor trailers out of the way. He indicated that this wouldn't be a problem, and as Mr. McCormick stated, he re-confirmed that we were going to be landing on the east side of the facility. This is not uncommon for things to change for projects we conduct and may have been a contributing factor in the overall event.

(Continued on page 11)

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

185 _____ Gallons

Fuel Type

☐ 80/87

☐ 115/145

☐ Jet B

☐ Other, specify _____

☐ 100 Low Lead

☒ Jet A

☐ JP8

☐ 100/130

☐ Jet A-1

☐ Automotive

Other Services, if Any, Prior to Departure

None

EVACUATION OF AIRCRAFT

Was an emergency evacuation of the aircraft performed? ☐ Yes ☒ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

Pilot and Mechanic exited the cockpit through the cockpit window entrance. The Mechanic in the cabin area exited out the main cabin door.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed

☐ Minor

☐ Substantial

☒ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

Moving forward, we will assess on how to conduct operations when it may be an difficult to establish a 100' by 150' Landing Zone. This could be done by sending crews out ahead of the aircraft when this could become a factor. Another option would be for the aircraft to leave the site and go to a airport location if the LZ is not what we expected or suitable. Over the past 8-10 years, MHA has developed and implemented new safety protocols into our everyday missions. We assess each risk that we come across and how we can mitigate it in order to complete the mission. Our SMS program is consistently evolving as our missions and environments we work in change. In the past 4 years, we have developed an Emergency Response Plan that came into play with this incident and now we can see what worked and what needs improvement. Even though we have a very active SMS program, it cannot fully eliminate the chance of an incident occurring, but what it does allow us to do is evaluate and reduce the risk, exposure and final outcome of situations we may encounter by crew recognition and hazard reporting.

We regret that this incident occurred, but Midwest will use it as a learning experience to ensure that this can be mitigated moving forward.

Jim Triggs
Director of Operations
Midwest Helicopter Airways, Inc.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE**Date of this Report**

11/14/2019
mm/dd/yyyy

Name of Pilot/Operator: _____**Signature:** _____

– or – ☐ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report**Name:** Midwest Helicopter Airways, Inc. (James S. Triggs)**Title:** Director of Operations / Chief Pilot**Signature:** _____

– or – ☒ Check here to electronically sign this document

FOR NTSB USE ONLY**NTSB Accident/Incident No.**

GAA20CA063

Reviewed by NTSB Regional Office

GAA

Name of Investigator

Eleazar Nepomuceno

Date Report Received

11/15/2019