



Photo 1 – View of damage to the airplane (Courtesy of FAA)



Photo 2 – View of damage to engine mount (Courtesy of Operator)