



Photo 1 – Flight Control Tubing



Photo 2 – Close-up of Fractured Tube



Photo 3 – Fractured Tube



Photo 4 – Aft Fractured End of Control Tube